



F379019

T.E.T.® THESE = THOSE

#10 Speed Spray Power Cleaner

PRODUCT DESCRIPTION:

An ultra concentrated spray and wipe cleaner. T.E.T. no-decision mixing provides a ready-to-use solution to clean and remove grease, ink marks, adhesives, tar, betadine, price stickers and other hard to remove soils. Safe for use on all hard surfaces, even engine blocks.

FEATURES:

Cost Effective:

One product removes ink marks, graffiti, grease and other soils on hard surfaces.

Environmentally Friendly:

Contains no "butyl". Non-flammable concentrate. Does not promote rust.

Reduces Labor:

One product replaces the need for multiple cleaners and simplifies training. Quickly removes many tough soils, including adhesives.

PRODUCT SPECIFICATIONS:

pH	11.0 ± 0.5
Appearance	Purple, Liquid
Physical State	Concentrated
Fragrance	Menthol
Freezing Point	About 32°F
Solubility in Water	Complete
Flash Point	171°F

INGREDIENTS:

Water	7732-18-5
Diproylene Glycol n-Butyl Ether ...	29911-28-2
Dipropylene glycol methyl ether ...	34590-94-8
Monoisopropanolamine	78-96-6
Undeceth-7	34398-01-1

DILUTIONS	HEALTH	FLAMMABILITY	REACTIVITY
CONCENTRATE	NFPA 3 HMIS	NFPA 0 HMIS	NFPA 0 HMIS
(1:8 RATIO)	NFPA 2 HMIS	NFPA 0 HMIS	NFPA 0 HMIS
(1:8 RAZÓN)			
PROPORCIÓN	SALUD	INFLAMABILIDAD	REACTIVIDAD

0	1	2	3	4
Minimal	Slight	Moderate	Serious	Severe
Mínimo	Mínimo	Moderar	Grave	Drástico

ECOLOGICAL INFORMATION:

- Contains No Phosphorus
- Concentrated; eliminates waste and provides source reduction.

T.E.T.® #10 Speed Spray Power Cleaner

FAST ACTING, SPRAY AND WIPE CLEANER

DIRECTIONS

USE INFORMATION

Always dilute in properly labeled quart bottles. Do not spray on electrical circuits. *Speed Spray Power Cleaner* is safe for use on most washable hard surfaces. It is best to pre-test on painted surfaces. Use on baked enamel, kick plates, switch plates, porcelain, glass, most plastic surfaces, industrial table tops, industrial counter tops, stainless steel, iron, aluminum, wheels, rubber, urethane or epoxy painted surfaces and other hard surfaces.

DIRECTIONS



1. REMOVE CAP **2. SQUEEZE** **3. POUR** **4. SPRAY** **5. WIPE**

DIRECTIONS

- 1. REMOVE CAP** and seal.
- 2. SQUEEZE BOTTLE** and fill the portion control cup according to soil conditions. Excess cleaner will automatically flow back into the bottle.
- 3. POUR** the contents of the cup into an empty, properly labeled quart bottle. Fill the quart bottle with cool tap water and attach a sprayer.
- 4. SPRAY** the surface to be cleaned.
- 5. WIPE** with a clean lint free cloth or paper towel. On problem soils allow the solution to soak a few minutes before wiping or rinsing.

NOTE: For heavy soils like adhesives and tar use 8 oz. per 32 oz. quart bottle (1:4 ratio). For medium soils such as spot/stain removal or as an engine degreaser use 4 oz. per 32 oz. quart bottle (1:8 ratio). For spray and wipe cleaning of light soils or use as a general degreaser use 1/2 oz. per 32 oz. quart bottle (1:64 ratio).

DANGER

Combustible liquid. Harmful if swallowed. Causes severe skin burns and eye damage. Causes serious eye damage. Harmful to aquatic life. Harmful to aquatic life with long lasting effects.

Prevention

Keep away from heat / sparks / open flames / hot surfaces. No smoking. Do not breathe mist or vapor. Wash thoroughly after handling. Do not eat, drink or smoke when using this product. Avoid release to the environment. Wear protective gloves / protective clothing / eye protection / face protection

Response

If swallowed: Rinse mouth. Do NOT induce vomiting. If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water / shower. If inhaled: Remove person to fresh air and keep comfortable for breathing. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a poison center / doctor. Specific treatment (see SDS). Wash contaminated clothing before reuse. In case of fire: Use appropriate media to extinguish.

Storage

Store in a well-ventilated place. Keep cool. Store locked up.

Disposal

Dispose of contents/container in accordance with local / regional / national / international regulations.

KEEP OUT OF REACH OF CHILDREN



PERSONAL PROTECTION:

Respiratory Protection: Not needed under normal conditions.

Ventilation: Use with adequate ventilation.

Eye Protection: Safety glasses are required.

Protective Gloves: Protective gloves are required.

Other Protective Clothing or Equipment: Wear clothing as necessary to prevent skin contact.

TRANSPORTATION

INFORMATION:

U.S. DOT - Proper Shipping

Name: Limited Quantity

Marine Pollutant: No

Franklin Cleaning Technology

One Fuller Way
Great Bend, KS 67530
United States
CHEMTREC (800) 424-9300
Emergency (620) 792-1711
24 hour Emergency (800) 424-9300
www.fullercommercial.com

F379019TDS-0315